

EXERCISE KAKAMA

Status Update Notice

Date:	22 June 2016
Time:	12:30pm
Notice Number:	CC-0027
Notice Type:	Status Update
Notice Issued To:	Stakeholders listed in Information Guide
Notice Copied To:	First Gas TSO
Date and Time Critical Contingency Declared:	09:30 on 22 June 2016
Event that caused Critical Contingency:	3 rd Party damage to the First Gas 100 pipeline between Turakina Main Line Valve and Raumai Scraper Station resulting in a gas escape and a breach of the pressure threshold at Waitangirua (Wellington).
CCO determination on Regional Critical Contingency Status:	Regional
Areas of transmission system affected:	The First Gas 100 and 700 pipelines and associated laterals south of Turakina to Wellington and east to Hastings.
CCO actions being taken to stabilise the gas system:	The CCO has declared a Critical Contingency and issued curtailment instructions to the industry to balance the supply and demand in the affected areas of the transmission system. These instructions will remain in effect until the underlying issue affecting supply is resolved.
Curtailment Directions issued by CCO:	<p>The CCO has issued curtailment instructions requiring all large and medium sized industrial or commercial consumers in Bands 3 and 4, plus all essential service consumers and small commercial consumers in Bands 5 and 6 supplied from the First Gas 100 and 700 pipelines and associated laterals south of Turakina to Wellington and east to Hastings to stop using gas immediately.</p> <p>This curtailment instruction affects:</p> <ul style="list-style-type: none"> • All Band 3 & 4 consumers such as dairy factories, pulp & paper processing, manufacturers, large fast food outlets, large retail and leisure facilities and glass houses. • All Band 5 & 6 consumers such as waste water treatment plants, restaurants, retail outlets, workshops etc. <p>There are no Band 0, 1 or 2 consumers supplied from this pipeline system so they are not affected.</p> <p>Consumers in Band 7 who have a Critical Care designation are not affected.</p>

EXERCISE KAKAMA

Details of Event resolution:	The pipeline owner, First Gas Ltd has advised that; “The damaged section of the pipeline has been isolated, made safe and repairs are underway. There have been no injuries as a result of this incident.” <i>Please contact First Gas Ltd (CEO Paul Goodeve 0275 675 161) for further information on the pipeline damage or estimated time to repair.</i>
Estimated Time to repair underlying problem:	At least 24 hours from when the critical contingency was declared.

This notice is supplementary to the other notices issued by the CCO during a critical contingency.

This notice does not contain any directions or declarations and is published to provide more information and forecasts about the status of the critical contingency.

The information contained in Status Update Notices is based on the best information/knowledge available to the CCO at the time of publication and may vary over the duration of the event as the situation changes/develops.

The CCO will issue advice of this Status Update to the stakeholders listed in the CCO Information Guide and publish this notice in the public domain of the CCO web site at <http://www.cco.org.nz>